

Inspection Report # 12



Project Reference Information

Date: July 11, 2017

Report #12

Client Name: York University

Reveal Project #2017025

Site Address: 4700 Keele Street, Farquharson Building

Project Name: Farquharson Renovation

Reveal Designate: Jeff Lainsbury

Contractor: Priestly Demolition

Time of Arrival on Site:
1:00 PM

of Workers:
N/A

Distribution List:

Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dicalis@priestly.ca

Summary of Work in Progress

Work in Progress	Location
Occupied Air Monitoring. PCM and Total Dust	Rm 016, 108, 209, 304

Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Work Area	Start Time	Flow Rate	Air Volume (L)	Result
001	Occupied	RM 016	Lab	2:30	15	645	<0.05
002	Occupied	Rm 108	Lab	2:40	15	654	<0.05
003	Occupied	RM 209	Lab	2:55	15	390	<0.05
004	Occupied	RM 304	Lab	3:20	15	645	<0.05

Summary of Total Dust Sample Collection Data

Sample #	Type	Sample Location	Work Area	Start Time	Min Mg/M ³	Max Mg/M ³	Average Mg/M ³
001	Occupied	RM 016	Lab	2:28	0.223	0.355	0.276
002	Occupied	Rm 108	Lab	2:45	0.081	0.158	0.118
003	Occupied	RM 209	Lab	2:56	0.046	0.061	0.051
004	Occupied	RM 304	Lab	3:09	0.031	0.039	0.035

Report # 12

Date: July 11, 2017

Client Name: York University



Itemized Inspection Report Summary

[illegible]