

Inspection Report # 14



Project Reference Information

Date: July 27, 2017

Report #14	Client Name: York University	Reveal Project #2017025
------------	------------------------------	-------------------------

Site Address: 4700 Keele Street, Farquharson Building

Project Name: Farquharson Renovation	Reveal Designate: Jeff Lainsbury
--------------------------------------	----------------------------------

Contractor: Priestly Demolition	Time of Arrival on Site: 09:15 AM	# of Workers: N/A
---------------------------------	-----------------------------------	-------------------

Distribution List:

Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress

Work in Progress	Location
Occupied Air Monitoring. PCM and Total Dust	R< 015, 108, 204, and 303

Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Work Area	Start Time	Flow Rate	Air Volume (L)	Result
CX296032	Blank	RM 015	Lab	10:10	15	0	2 fibers
CX296052	Occupied	RM 015	Lab	10:10	15	420	<0.05
CX296044	Occupied	RM 108	Lab	10:12	15	420	<0.05
CX295992	Occupied	RM 204	Lab	10:45	15	420	<0.05
CX296045	Occupied	RM 303	Lab	10:47	15	420	<0.05

Summary of Total Dust Sample Collection Data

Sample #	Type	Sample Location	Work Area	Start Time	Min Mg/M ³	Max Mg/M ³	Average Mg/M ³
001	Occupied	RM 015	Lab	10:20	0.025	0.043	0.035
002	Occupied	RM 108	Lab	10:35	0.033	0.067	0.045
003	Occupied	RM 204	Lab	10:45	0.039	0.47	0.109
004	Occupied	RM 303	Lab	10:55	0.022	0.041	0.028

Report # 14

Date: July 27, 2017

Reveal
Environmental Inc.

[illegible]