

Inspection Report # 16



Project Reference Information

Date: August 4, 2017

Report #16

Client Name: York University

Reveal Project #2017025

Site Address: 4700 Keele Street, Farquharson Building

Project Name: Farquharson Renovation

Reveal Designate: Jeff Lainsbury

Contractor: Priestly Demolition

Time of Arrival on Site:
12:00 PM

of Workers:
N/A

Distribution List:

Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress

Work in Progress	Location
Occupied Air Monitoring. PCM and Total Dust	Corridor at Rm 004, Rm 110B, Rm 209, Rm 306

Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Work Area	Start Time	Flow Rate	Air Volume (L)	Result
004	Occupied	Corridor outside RM 004	Corridor	2:23	15	450	<0.05
001	Occupied	RM 110B	Lab	2:32	15	450	<0.05
002	Occupied	RM 209	Lab	2:34	15	825	<0.05
003	Occupied	RM 306	Lab	2:39	15	900	<0.05

Summary of Total Dust Sample Collection Data

Sample #	Type	Sample Location	Work Area	Start Time	Min Mg/M ³	Max Mg/M ³	Average Mg/M ³
001	Occupied	Corridor outside RM 004	Corridor	2:40	0.038	0.056	0.046
002	Occupied	RM 110 B	Lab	2:56	0.028	0.032	0.029
003	Occupied	RM 209	Lab	3:08	0.029	0.031	0.030
004	Occupied	RM 306	Lab	3:26	0.001	0.053	0.015

