

Inspection Report # 16



Project Reference Information

Date: August 2, 2017

Report #6	Client Name: York University	Reveal Project #2017025
-----------	------------------------------	-------------------------

Site Address: 4700 Keele Street, Farquharson Building

Project Name: Farquharson Renovation	Reveal Designate: Jeff Lainsbury
--------------------------------------	----------------------------------

Contractor: Priestly Demolition	Time of Arrival on Site: 1:00 PM	# of Workers: N/A
---------------------------------	-------------------------------------	----------------------

Distribution List:

Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress

Work in Progress	Location
Type 3 Visual Clearance inspection	Penthouse Mechanical Room

Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Work Area	Start Time	Flow Rate	Air Volume (L)	Result

Report # 16

Date: August 2, 2017

Client Name: York University



Itemized Inspection Report Summary

[illegible]