## Inspection Report # 19



Project Reference Information		Date: August 8, 2017		
Report #19	Client Name: York University		Reveal Project #2017025	
Site Address: 4700 Keele Street, Farquharson Building				
Project Name: Farquharson Renovation		Reveal Designate: Jeff Lainsbury		
Contractor: Priestly Demolition		Time of Arrival on Site:	# of Workers:	

Distribution List:		
Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress	
Work in Progress	Location
Type 3 air Clearance inspection retest	Penthouse Mechanical Room

Summary of <b>PCM</b> Sample Collection Data							
Sample	Type	Sample location	Work	Start	Flow	Air	Result
#			Area	Time	Rate	Volume	
					(L/min)	(L)	
001	Clearance	Mechanical Penthouse	Type 3	10:15	15	2400	<0.01
002	Clearance	Mechanical Penthouse	Type 3	10:15	15	2400	<0.01
003	Clearance	Mechanical Penthouse	Type 3	10:15	15	2400	<0.01
004	Blank						1 fibres

Project Name: Farquharson Renovation

Report # 19

Site Address: 4700 Keele, Farquharson Building

Date: August 8, 2017

Client Name: York University



Itemi	zed Inspection Report Summary
Item#	Comments
1.0	Air clearance re-testing performed August 5, 2017. All air samples were within acceptable limitations, and below clearance criteria specified in Ontario Regulation 278/05. Verbal permission to begin teardown of enclosure was provided to abatement foreman at 11:15 AM