

Inspection Report # 23



Project Reference Information		Date: September 28, 2017
Report #23	Client Name: York University	Reveal Project #2017025
Site Address: 4700 Keele Street, Farquharson Building		
Project Name: Farquharson Renovation	Reveal Designate: Jeff Lainsbury	
Contractor: Priestly Demolition	Time of Arrival on Site: 12:00 PM	# of Workers: N/A

Distribution List:

Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress

Work in Progress	Location
Occupied Air Monitoring. PCM and Total Dust	RM 105, Corridor at 005, RM 204, Corridor at RM 305

Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Work Area	Start Time	Flow Rate	Air Volume (L)	Result
001	Occupied	RM 105	Lab	12:20	15	450	<0.05
002	Occupied	Corridor @ RM 005	Corridor	12:25	15	525	<0.05
003	Occupied	RM 204	Lab	12:30	15	675	<0.05
004	Occupied	Corridor @ RM 305	Corridor	12:35	15	750	<0.05

Summary of Total Dust Sample Collection Data

Sample #	Type	Sample Location	Work Area	Start Time	Min Mg/M ³	Max Mg/M ³	Average Mg/M ³
001	Occupied	RM 105	Lab	12:50	0.006	0.009	0.007
002	Occupied	Corridor @ RM 005	Corridor	01:00	0.033	0.117	0.066
003	Occupied	RM 204	Lab	01:15	0.008	0.012	0.009
004	Occupied	Corridor at RM 305	Corridor	1:25	0.126	0.165	0.144

