

# Inspection Report # 24



## Project Reference Information

Date: October 5, 2017

Report #24

Client Name: York University

Reveal Project #2017025

Site Address: 4700 Keele Street, Farquharson Building

Project Name: Farquharson Renovation

Reveal Designate: Jeff Lainsbury

Contractor: Priestly Demolition

Time of Arrival on Site:  
12:30 PM

# of Workers:  
N/A

## Distribution List:

Name	Company	Email
Adriano Morassutti	York University	<a href="mailto:adrianom@yorku.ca">adrianom@yorku.ca</a>
Earnest Murdoch	Gillam Group	<a href="mailto:emurdoch@gillamgroup.com">emurdoch@gillamgroup.com</a>
Devin Ricalis	Priestly Demolition	<a href="mailto:dricalis@priestly.ca">dricalis@priestly.ca</a>

## Summary of Work in Progress

Work in Progress	Location
Occupied Air Monitoring. PCM and Total Dust	RM 108, RM 016, RM 208, RM 302

## Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Work Area	Start Time	Flow Rate	Air Volume (L)	Result
001	Occupied	RM 108	Lab	12:36	15	390	<0.05
002	Occupied	RM 016	Lab	12:42	15	540	<0.05
003	Occupied	RM 208	Lab	12:50	15	645	<0.05
004	Occupied	RM 302	Lab	12:55	15	720	<0.05

## Summary of Total Dust Sample Collection Data

Sample #	Type	Sample Location	Work Area	Start Time	Min Mg/M <sup>3</sup>	Max Mg/M <sup>3</sup>	Average Mg/M <sup>3</sup>
001	Occupied	RM 108	Lab	01:03	0.004	0.008	0.005
002	Occupied	RM 016	Lab	01:18	0.005	0.008	0.006
003	Occupied	RM 208	Lab	01:33	0.017	0.030	0.024
004	Occupied	RM 302	Lab	01:43	0.017	0.036	0.024

