

Inspection Report # 25



Project Reference Information

Date: October 11, 2017

Report #25

Client Name: York University

Reveal Project #2017025

Site Address: 4700 Keele Street, Farquharson Building

Project Name: Farquharson Renovation

Reveal Designate: Jeff Lainsbury

Contractor: Priestly Demolition

Time of Arrival on Site:
11:30 AM

of Workers:
N/A

Distribution List:

Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress

Work in Progress	Location
Occupied Air Monitoring. PCM and Total Dust	RM 110, RM 010, Corridor at RM 206, RM 306

Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Work Area	Start Time	Flow Rate	Air Volume (L)	Result
001	Occupied	RM 110	Lab	11:45	15	450	<0.05
002	Occupied	RM 010	Lab	11:52	15	459	<0.05
003	Occupied	Corridor @ RM 206	Lab	11:58	15	615	<0.05
004	Occupied	RM 306	Lab	12:04	15	735	<0.05

Summary of Total Dust Sample Collection Data

Sample #	Type	Sample Location	Work Area	Start Time	Min Mg/M ³	Max Mg/M ³	Average Mg/M ³
001	Occupied	RM 110	Lab	12:15	0.007	0.012	0.009
002	Occupied	RM 010	Lab	12:26	0.014	0.029	0.019
003	Occupied	Corridor @ RM 206	Lab	12:39	0.010	0.062	0.025
004	Occupied	RM 306	Lab	12:53	0.025	0.088	0.069

