

Inspection Report # 26



Project Reference Information

Date: October 18, 2017

Report #26

Client Name: York University

Reveal Project #2017025

Site Address: 4700 Keele Street, Farquharson Building

Project Name: Farquharson Renovation

Reveal Designate: Jeff Lainsbury

Contractor: Priestly Demolition

Time of Arrival on Site:
12:45 PM

of Workers:
N/A

Distribution List:

Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress

Work in Progress	Location
Occupied Air Monitoring. PCM and Total Dust	RM 105, Corridor @ Rm 007, Corridor @ Rm 205, Rm 306

Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Work Area	Start Time	Flow Rate	Air Volume (L)	Result
001	Occupied	RM 105	Lab	13:00	15	450	<0.05
002	Occupied	Corridor @ RM 007	Lab	13:05	15	525	<0.05
003	Occupied	Corridor @ RM 205	Lab	13:10	15	660	<0.05
004	Occupied	RM 306	Lab	13:15	15	750	<0.05

Summary of Total Dust Sample Collection Data

Sample #	Type	Sample Location	Work Area	Start Time	Min Mg/M ³	Max Mg/M ³	Average Mg/M ³
001	Occupied	RM 105	Lab	13:30	0.014	0.019	0.016
002	Occupied	Corridor @ RM 007	Lab	13:40	0.031	0.046	0.038
003	Occupied	Corridor @ RM 205	Lab	13:54	0.016	0.025	0.019
004	Occupied	RM 306	Lab	14:05	0.032	0.071	0.043

Report # 26

Date: Oct. 18, 2017

Client Name: York University



Itemized Inspection Report Summary

[illegible]