

Inspection Report # 27



Project Reference Information

Date: October 27, 2017

Report #25 Client Name: York University Reveal Project #2017025

Site Address: 4700 Keele Street, Farquharson Building

Project Name: Farquharson Renovation Reveal Designate: Jeff Lainsbury

Contractor: Priestly Demolition Time of Arrival on Site: 11:45 AM # of Workers: N/A

Distribution List:

Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress

Work in Progress	Location
Occupied Air Monitoring. PCM and Total Dust	RM 021, Corridor at RM 106, RM 210, Corridor @ RM A304

Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Work Area	Start Time	Flow Rate	Air Volume (L)	Result
001	Occupied	RM 021	Lab	11:55	15	450	<0.05
002	Occupied	Corridor @ RM 106	Lab	12:02	15	405	<0.05
003	Occupied	RM 210	Lab	11:58	15	780	<0.05
004	Occupied	Corridor @ RM A304	Lab	12:04	15	735	<0.05

Summary of Total Dust Sample Collection Data

Sample #	Type	Sample Location	Work Area	Start Time	Min Mg/M ³	Max Mg/M ³	Average Mg/M ³
001	Occupied	RM 021	Lab	12:25	0.005	0.010	0.007
002	Occupied	Corridor @ RM 106	Lab	12:26	0.529	0.948	0.754
003	Occupied	RM 210	Lab	12:50	0.548	0.924	0.719
004	Occupied	Corridor @ RM A304	Lab	13:03	0.574	0.988	0.749

