

# Inspection Report #9



Project Reference Information		Date: July 6, 2017
Report # 9	Client Name: York University	Project #: 2017025
Site Address: 4700 Keele Street, Toronto		
Project Name: Farquharson Life Science Renovation		Reveal Designate: Jeff Lainsbury
Contractor: Priestly Demolition	Time of Arrival on Site: 9:00 AM	# of Workers: N/A

Distribution List:		
Name	Company	Email
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Adriano Morassutti	York University	adrianom@yorku.ca
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress	
Work in Progress	Location
Type 3 Visual Clearance	North Corridor outside of 011
Type 3 Air Monitoring Clearance	North Corridor outside of 011

Summary of Sample Collection Data							
Sample #	Sample Type	Description of Work	Start Time	Flow Rate (L/min)	Sample Period (min)	Air Volume (L)	Result (Fibre/mL)
001	Clearance	No work in progress	9:08 AM	15	160	2400	<0.01
002	Clearance	No work in progress	9:08 AM	15	160	2400	<0.01
003	Clearance	No work in progress	9:08 AM	15	160	2400	<0.01

Reveal checked and calibrated the air sampling pump before and after air sample collection

