

Inspection Report # 22a



Project Reference Information

Date: August 13, 2017

Report #22a

Client Name: York University

Reveal Project #2017025

Site Address: 4700 Keele Street, Farquharson Building

Project Name: Farquharson Renovation

Reveal Designate: Jeff Lainsbury

Contractor: Priestly Demolition

Time of Arrival on Site:
10:00 AM

of Workers:
N/A

Distribution List:

Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress

Work in Progress	Location
Type 3 Air Monitoring Clearance inspection	Mechanical Room 007 – Sprayed fireproofing from bottom of mechanical shaft

Summary of PCM Sample Collection Data

Sample #	Type	Sample location	Start Time	Flow Rate	Air Volume (L)	Result
001/13	Clearance	Mechanical Room 007	10:15	15	2400	<0.01
002/13	Clearance	Mechanical Room 007	10:15	15	2400	<0.01
003/13	Clearance	Mechanical Room 007	10:15	15	2400	<0.01
004/13	QC	Blank	N/A	N/A	N/A	0 Fibres

Report # 22a

Date: August 13, 2017

Client Name: York University



Itemized Inspection Report Summary

[illegible]