

Inspection Report # 34



Project Reference Information		Date: February 26, 2018
Report #34	Client Name: York University	Reveal Project #2017025
Site Address: 4700 Keele Street, Farquharson Building		
Project Name: Farquharson Renovation	Reveal Designate: Jeff Lainsbury	
Contractor: Priestly Demolition	Time of Arrival on Site: 07:00 AM	# of Workers: ~4

Distribution List:		
Name	Company	Email
Adriano Morassutti	York University	adrianom@yorku.ca
Earnest Murdoch	Gillam Group	emurdoch@gillamgroup.com
Devin Ricalis	Priestly Demolition	dricalis@priestly.ca

Summary of Work in Progress	
Work in Progress	Location
Type 3 Visual/Air Monitoring Inspection Fan S1/S2	Mechanical Room 007

Summary of PCM Sample Collection Data						
Sample #	Type	Sample location	Start Time	Flow Rate (L/min)	Air Volume (L)	Result (Fibres/mL)
001	Clearance	Type 3 Fan S1/S2	7:20	15	3000	<0.01
002	Clearance	Type 3 Fan S1/S2	7:20	15	3000	<0.01
003	Clearance	Type 3 Fan S1/S2	7:20	15	3000	<0.01

